




CEILING MOUNTING



STEP9 Locate the power source and mount the metal cap to cover it. Guide the screw terminal true the big hole.



STEP11 Cover the metal cap by the pressing the rubber cover over it



WALL MOUNTING

Step1 Locate the right position and mark the two screw spots.
Step2 Drill two holes NOTE: use the right drill for the specific surface.
Step3 Fix the two adapters to the surface by using the right screws and plugs.

